

FIG. 1  
(Prior Art)





FIG. 7

FIG. 2  
(Prior Art)





FIG. 8




FIG. 4  
(Prior Art)




FIG. 10




FIG. 3  
(Prior Art)




FIG. 9

Axial  
Conductance  
(L/s)





FIG. 5  
(Prior Art)

Axial  
Conductance  
(L/s)



Axial Gap (Inches)

FIG. 11




FIG. 6  
(Prior Art)




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17